

### MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

### **DATAMASTER MAINTENANCE REPORT**

RECEIVED

REPORT #6

By Carol Day at 4:00 pm, Aug 12, 2014

Complete this report at the time of the regular mo Complete this report whenever the instrument is a Retain the original and send a copy within 15 day	serviced or repaire	ed and whenever it is	placed into ser	ō days). vice.	
DATAMASTER SN NAME OF AGENCY			DATE OF INSPECT		
202004 MSHP-D  LOCATION OF INSTRUMENT (STREET AND CITY) 10 CO N. BOONEVILLE AVE.			08-03-20/4 TIME OF INSPECTION		
GREENE COUNTY SPITTING	GETELD. V	MA LEDOS			
CHECKLIST: Place a mark in the box by each item where determined.) Unmarked items must be corn	if found to be sati ected before usin	sfactory or if operating g instrument.	within establis	shed limits. (	Write in observed values
☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHE	ED)	DATE AND TIME (	from printout)	08/03/14	1745
<b>⊠</b> COMPUTER		DETECTOR			
PROGRAM		FILTERS			
HEATERS SAMPLE CHAMBER4	<u>-9</u> •c	QUARTZ STAN	IDARD		
FLOW DETECTOR		CALIBRATION			
PUMP HIGH SPEED		PRINTER			
INDICATOR LIGHTS			1-200-1	·	
SIMULATOR SOLUTION SUPPLIER GUTH	LABORATOR	PES TAKLOT# 1	3290	EXP. DA	TE <u>/0 - 29 - /5</u>
$\boxtimes$ SIMULATOR TEMP (34°C ± 0.2°C) $34.2$ °C SIMULATOR SN $G/(082)$ EXP. DATE $10-31-14$					
CALIBRATION CHECK - (ONLY ONE STAND	ARD IS TO BE U	SED PER MAINTEN	ANCE REPOR	T)	
Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)					
0.100% STANDARD - MUST READ BETW 0.080% STANDARD - MUST READ BETW 0.040% STANDARD - MUST READ BETW	EEN 0.076% AND	0.084% INCLUSIVE			
TEST 1 0 .098 TEST	2 0,09	9	TEST 3 🖝	0.10	Ø
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)					
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)					
REFUSALS / (004) O (.050	09) 3	(.1014)	(.1519)	7	رځ OVER .19
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS  0:10 SOLUTION					
MEETS MOHSS REQUEREMENTS					
NCDECTING OFFICE					
INSPECTING OFFICER SIGNATURE		PRINT FULL NAM			
· CPL. Kr. Water		THIN TOLE NAME	1, .	NALT	BAC
1240078 03-0	7-2016	TELEPHONE NUM	BEA	20.10	
2875 Jan	conoi Program, m nes Blvd. uff MO 63901	no nehattineut of Hea	ıın and Senior	Services, S	outheast District Office



### CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 13290 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography on October 31, 2013, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1202% (w/vol) ethyl alcohol. The expiration date for this lot number is October 29, 2015 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.

### Face This Side Down - This Edge In First

# **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 202004 08/03/14 17:45

### --- DIAGNOSTIC CHECK ---

COMPUTER:

OKAY

PROGRAM (04-07-2009):

OKAY

HERTERS

SAMPLE CHAMBER:

49c

FLOW DETECTOR:

OKAY

PUHF

HIGH SPEED:

OKAY

DETECTOR:

ÜKÄY

FILTERS:

OKAY

QUARTZ STANDARD:

OKAY

CALIBRATION:

OKAY'

### PRINTER TEST

!"#\$%&(()\*+.-./0123456789;;<=>?@ABCDEFG HIJKLMMOPQRSTUVWXYZ[\]^\_'abcdefqhi.iklmno parstuvwxyz(|)+~ Face This Side Down - This Edge In First

# **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 202004 08/03/14

TESTING OFFICER:
WALTERS/K/D
OFFICER 1.D.: 674
PERMIT NUMBER: 240078
EXPIRATION DATE: 03/07/16
MISCELLANEOUS DATA:
MONTHLY MAINTENANCE

#### --- SUPERVISOR MODE ---

BLANK TEST	, 999	17153
INTERMAL STANDARD	VERIFIED	17:53
EXTERNAL STANDARD	.098	17:53
BLANK TEST	, 909	17454
EXTERMAL STANDARD	, 899	17:54
BLANK TEST	.000	17:55
EXTERNAL STANDARD	, 198	17:55
BLANK TEST	. មិនម	17:56

M = 3 SIM. = .1 AVG. = .099

Operator Signature CALKN Watto 674

Operator Signature CALL KN With 674

2208-02

Face This Side Down - This Edge In First

### **BAC DataMaster Evidence Ticket**

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 202004 08/03/14

ARREST TIME: 17:30 SUBJECT NAME: DOEZJZJ DOB: 11/11/11 SEX: M STATE/D.L.: MO/123456789 ARRESTING OFFICER: WALTERS/K/0 OFFICER I.D.: 674 TESTING OFFICER: SAME OFFICER 1.D.: 674 PERMIT NUMBER: 240078 EXPIRATION DATE: 03/07/16 MISCELLAMEOUS DATA: REI TEST

--- BREATH AMALYSIS ---

BLANK TEST

.000

17:59

INTERNAL STANDARD

VERIFIED

RADIO INTERFERENCE

17:59

Operator Signature Coll. W. W. W. W. D. 74



### STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES
BREATH ALCOHOL PROGRAM



## PERMIT TYPE II

## KENNETH D WALTERS

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

## DATAMASTER, INTOX DMT

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections 577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.

DATE3	3/7/2014	want
		DIRECTOR OF STATE PUBLIC HEALTH LABORATORY
NUMBER 2	440078	Dal Vasterly
EXPIRES 3	/7/2016	
		DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES

MO 680-0771 (6-10)

LAB-4 (R6-10)

